

# Rutin izleme Kapatma Kontrolü (Seal-Check)

**4a medical**<sup>®</sup>  
supporting healthcare



Rutin İzleme

# Kapatma Kontrolü

4a medical®  
supporting healthcare



EN ISO 11607-  
2'ye uygun olarak  
belirtilen kapatma  
geniřliđi iin sađlam  
kapatma.



6.061.017

PEEL

Sealing Machine · Siegelgerät Apareil de Scellage · Máquina selladora	Location · Standort Site · Ubicación	For Approval · Freigabe Autorisation · Habilitación	Date · Datum Date · Fecha	Remarks · Bemerkungen Remarques · Nota

Seal Check

hawo

T +49 (0) 6261/9770-0 · F +49 (0) 6261/62015 · info@hawo.com · www.hawo.com

No usar si el papel o el sellado se encuentra deteriorado  
Non utilizzare se la confezione è danneggiata

Kanallar ya da  
açık kapamalar.



6.061.017

PEEL ↑

Sealing Machine · Siegelgerät  
Apareil de Scellage · Máquina selladora

Location · Standort  
Site · Ubicación

For Approval · Freigabe  
Autorisation · Habilitación

Date · Datum  
Date · Fecha

Remarks · Bemerkungen  
Remarques · Nota


↑ Seal Check ↓

hawo

T +49 (0) 6261/9770-0 · F +49 (0) 6261/62015 · info@hawo.com · www.hawo.com

No usar si el papel o el sellado se encuentra deteriorado  
Non utilizzare se la confezione è danneggiata

Malzemenin  
delaminasyonu veya  
ayrılması/sıcaklığı veya  
temas basıncı çok düşük.



PEEL ↑

6.061.017


Sealing Machine · Siegelgerät Apareil de Scellage · Máquina selladora	Location · Standort Site · Ubicación	For Approval · Freigabe Autorisation · Habilitación	Date · Datum Date · Fecha	Remarks · Bemerkungen Remarques · Nota
--	---	--	------------------------------	---

Seal Check

hawo

T +49 (0) 6261/9770-0 · F +49 (0) 6261/62015 · info@hawo.com · www.hawo.com

No usar si el papel o el sellado se encuentra deteriorado  
Non utilizzare se la confezione è danneggiata



Delinmeler  
ya da  
yırtılmalar

6.061.017

PEEL ↑

h

Sealing Machine · Siegelgerät Appareil de Scellage · Máquina selladora	Location · Standort Site · Ubicación	For Approval · Freigabe Autorisation · Habilitación	Date · Datum Date · Fecha	Remarks · Bemerkungen Remarques · Nota
---	---	--	------------------------------	---

6.061.017


Seal Check

hawo

T +49 (0) 6261/9770-0 · F +49 (0) 6261/62015 · info@hawo.com · www.hawo.com

No usar si el papel o el sellado se encuentra deteriorado  
Non utilizzare se la confezione è danneggiata

Sıcaklık veya  
temas basıncı  
çok yüksek.



6.061.017

PEEL

Sealing Machine · Siegelgerät Apareil de Scellage · Máquina selladora	Location · Standort Site · Ubicación	For Approval · Freigabe Autorisation · Habilitación	Date · Datum Date · Fecha	Remarks · Bemerkungen Remarques · Nota

Seal Check

hawo

T +49 (0) 6261/9770-0 · F +49 (0) 6261/62015 · info@hawo.com · www.hawo.com

No usar si el papel o el sellado se encuentra deteriorado  
Non utilizzare se la confezione è danneggiata